



Refit cutouts

Coat bulkhead edge and cutout mounting screws with mold release coat mating edges with filled epoxy and align outer surfaces after cure disassemble and cleanup.

Atlas

PP1

Bulkhead

Refit cutouts

Drawing No ag0450h

27 Feb 03